

ERA23FA384

INVESTIGATION PHOTOS

Photo Array




Photo 1: Airplane Wreckage Being pulled from the Lake (Textron)



Photo 2: Airplane Wreckage Being pulled from the Lake (Textron)



Photo 3: Front View of Engine and Propeller (NTSB)



Photo 4: Rear View of Engine (NTSB)