

ERA23LA011

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Main Wreckage (Courtesy of FAA)



Photograph 3 - Main Wreckage (Courtesy of FAA)



Photograph 4 - Fuselage (NTSB Photo)



Photograph 5 - Tail Boom and Empennage (NTSB Photo)



Photograph 6 - Main Rotor (NTSB Photo)



Photograph 7 - Engine (NTSB Photo)