

ERA23LA013

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Cockpit (Courtesy of FAA)



Photograph 3 - Separated Canopy Sections (Courtesy of FAA)



Photograph 4 - Stop Drill Hole (Courtesy of FAA)