



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA015



Photo 1 – View of Airplane from Right Side (Courtesy of Pilot)



Photo 2 – View of Airplane from Front (Courtesy of Pilot)



Photo 3 – View of Airplane from Left Side (Courtesy of Pilot)



Photo 4 – View of Airplane from Rear – Note Damage to Right Wing (Courtesy of Pilot)