



Photo 1 – Broken Engine Mount (FAA Photo)




Photo 2 – Broken Engine Mount (FAA Photo)



Photo 3 – Accident airplane on ramp (FAA Photo)