



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA017



Photo 1 – View of Damaged Right Horizontal Stabilizer (Photo Courtesy of Embry Riddle Aeronautical University)



Photo 2 – Front View of Damaged Right Horizontal Stabilizer (Courtesy of Embry Riddle Aeronautical University)