



Photo 1 – FAA Digital Photograph. View Showing the Impact on the Runway.



Photo 2 – FAA Digital Photograph. View Taken Behind Left Wing Near Wing Root Looking Forward. Note Structural Damage to the Left Wing.



Photo 3 – FAA Digital Photograph. View Showing the Internal Structural Damage to the Left Wing.