



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA23LA031**



**Photo 1 – View of Airplane from Front Left (Courtesy of FAA)**



**Photo 2 – Damage to Left Wingtip (Courtesy of FAA)**



**Photo 3 – Closeup of Damage to Left Wing – Note Winkling in Skin (Courtesy of FAA)**



**Photo 4 – Damage to Left Horizontal Stabilizer – Note Winkling in Skin (Courtesy of FAA)**



**Photo 5 – View of Damage to Left Main Landing Gear (Courtesy of FAA)**



**Photo 6 – Closeup View of Damage to Left Main Landing Gear (Courtesy of FAA)**