



Photo 1 – main wreckage, right wing view (FAA)



Photo 2 – main wreckage, right side view, (FAA)



Photo 3 – Discolored crankshaft (FAA)



Photo 4 – No. 1 connecting rod with piston (FAA)