



Photo 1 – Accident Site (FAA Photo)



Photo 2 – Engine Mount Damage (FAA Photo)



Photo 3 – Engine Mount Damage (FAA Photo)



Photo 4 – Left wing damage (FAA Photo)



Photo 5 – Left wing damage (FA Photo)



Photo 6 – Left wing damage (FAA Photo)



Photo 7 – Vertical stabilizer and rudder damage (FAA Photo)