



Photo 1 – Damage to left elevator (Pilot Photo)



Photo 2 - Damage to left elevator (Pilot Photo)



Photo 3 - Damage to left elevator (Pilot Photo)