

ERA23LA040

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wide view of wreckage path and ground scars leading up to airplane. (Courtesy of FAA)



Photograph 2 - Left view of airplane showing overall damage. (Courtesy of FAA)



Photograph 3 - Aft view of airplane looking forward. (Courtesy of FAA)



Photograph 4 - Right profile view of entire airplane at accident site. (Courtesy of FAA)



Photograph 5 - Engine compartment and propeller damage. (Courtesy of FAA)



Photograph 6 - Cockpit instrument panel and fuel selector. (Courtesy of FAA)



Photograph 7 - Electronic engine monitor displaying fuel (Courtesy of FAA)