



Photo 1 – Accident Site (FAA Photo)



Photo 2 - Fuselage Damage (FAA Photo)



Photo 3 – Fuselage Damage (FAA Photo)



Photo 4 - Airframe Parachute Compartment and Mount (FAA Photo)



Photo 5 – Fuel Gauge Showing No Fuel (Right Rudder Aviation Photo)




Photo 6 – Fuel Gauge Showing No Fuel (Right Rudder Aviation Photo)




Photo 7 – In Line Fuel Filter Showing No Fuel (Right Rudder Aviation Photo)




Photo 8 – In Line Fuel Filter Showing No Fuel (Right Rudder Aviation Photo)