



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA052



Photo 1 – View of Airplane at Accident Site (Courtesy of FAA)



Photo 2 – View of Airplane’s Left Side – Note Damage to Left Wing (Courtesy of FAA)



Photo 3 – Closeup View of Damage to Left Wing (Courtesy of FAA)



Photo 5 – View of Airplane at Accident Site – Note Separated Wheel in Foreground (Courtesy of FAA)



Photo 6 – Airplane Path from Runway to Accident Site (Photo Courtesy of FAA)