



Photo 1 – FAA Digital Photograph. Right Side View of the Wreckage at the Accident Site.



Photo 2 - FAA Digital Photograph. Left Side View of the Wreckage at the Accident Site. Note the Substantial Damage to the Left Wing.



Photo 3 – FAA Digital Photograph. Right Side View of the Fuselage Aft of the Wing Center Section. Note the Substantial Damage.



Photo 4 – ScreenShot From Video Provided by Pilot. View of the Fuel Gauges Taken During Engine Run Before Accident Flight.