



Photo 1 – Damaged Runway Light (Photo Courtesy of FAA)



Photo 2 – Empennage Damage (Photo Courtesy of FAA)