



Photo 1 – Accident site, airplane came to rest inverted (FAA Photo)



Photo 2 – Damage to the right wing (FAA Photo)



Photo 3 – Damage to right wing (FAA Photo)



Photo 4 – Impact separated wreckage of right wing (FAA Photo)



Photo 5 – Damage to left wing (FAA Photo)



Photo 6 – Impact separated tail section, found in a tree about 40 yards from main wreckage (FAA Photo)