



## **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA23LA084**



**Photo 1 – View of Helicopter at Accident Site (Courtesy of FAA)**



**Photo 2 – View of Helicopter Main Rotor Mast Pylon Attachment to Fuselage (Courtesy of FAA)**



**Photo 3 – View of Tail Boom Attachment to Fuselage (Courtesy of FAA)**



**Photo 4 – View of Tail Rotor (Courtesy of FAA)**



**Photo 5 – View of Helicopter at Accident Site – Note the Skids (Courtesy of FAA)**