



Photo 1 – Left wing damage (FAA Photo)



Photo 2 – Left wing damage (FAA Photo)



Photo 3 – Left wing damage (FAA Photo)



Photo 4 – Left wing damage to rib and spar (FAA Photo)



Photo 5 – Wrinkling of skin aft of the forward spar (FAA Photo)