

ERA23LA100

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photo of airplane shortly after accident (Courtesy of FAA/Witness)



Photograph 2 - Photo of cockpit area (Courtesy of FAA)



Photograph 3 - Photo of aft fuselage and engine (Courtesy of FAA)