



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA102



Photo 1 – View of Fuselage from Left Side (Courtesy of FAA)



Photo 2 – View of Fuselage Right Side – Note Damage (Courtesy of FAA)




Photo 3 – Closeup of Damage to Fuselage (Courtesy of FAA)



Photo 4 – Damage to Empennage (Courtesy of FAA)