



Photo 1 – AMF Aviation Digital Photograph. Left Forward Quartering View of the Inverted Airplane at the Accident Site. Note the Compression Wrinkles in the Lower Skin of the Left Wing Outboard of the Lift Strut.



Photo 2 - AMF Aviation Digital Photograph. Right Side View of the Inverted Airplane at the Accident Site. Note the Damage to the Right Lift Strut, Compression Wrinkles in the Right Wing Lower Skin, and Damage to the Aft Fuselage.