



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Aft Fuselage Damage (Left Side) – Courtesy of FAA



Photo 3 – Nose Landing Gear and Belly Damage (Left Side) – Courtesy of FAA



Photo 4 – Left Wing Damage – Courtesy of FAA



Photo 5 – Right Wing Damage – Courtesy of FAA



Photo 6 – Close Up of Right Wing Damage – Courtesy of FAA



Photo 7 – Damage to Right Front Portion of Engine Cowling



Photo 8 – Aft Fuselage Damage (Right Side)



Photo 9 -Close Up of Aft Fuselage Damage (Left Side)



Photo 10 – Close Up of Belly Damage



Photo 11 – Right Side of Belly



Photo 12 – Master Cylinder (Right Side)



Photo 13 – Right Main Wheel Brake Assembly



Photo 14 – Right Brake Caliper



Photo 15 – Right Brake Caliper Upper Piston



Photo 16 – Leakage from Upper Piston



Photo 17 –Brake Linings from Right Main Brake Caliper



Photo 18 – Close Up of Brake Linings (Pressure Plate Side)



Photo 19 - Close Up of Brake Linings (Backing Plate Side)



Photo 20 - Upper Piston Seal