



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA145



Photo 1 – View of Accident Airplane From Front Right (Courtesy of FAA)



Photo 2 – View of Damage to Airplane's Firewall (Courtesy of FAA)