



Photo 1 – View of front of airplane collided with tree. (FAA photo)



Photo 2 – Left side view of airplane showing cockpit damage. (FAA Photo)