



Photo 1 – Left Side View of Airplane in a Ditch (FAA)



Photo 2 – Left Side View of Airplane in a Ditch (FAA)



Photo 3 - Damage to LH Wing at Root (FAA)



Photo 4 – Damage to LH Wing at Root (FAA)