



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA167



Photo 1 – View of Accident Airplane – Note Damage to Left Wing (Courtesy of FAA)



Photo 2 – View of Fuselage Right Side – Note Damage to Right Wing Strut (Courtesy of FAA)