

ERA23LA180

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane from front right (Courtesy of FAA)



Photograph 2 - Airplane from aft (Courtesy of FAA)



Photograph 3 - Airplane from front left (Courtesy of FAA)



Photograph 4 - Left wing from aft (Courtesy of FAA)



Photograph 6 - Inboard left wing from front (Courtesy of FAA)



Photograph 7 - Left Main Landing Gear Trunnion (Courtesy of FAA)



Photograph 8 - Left Main Landing Gear Scissor (Courtesy of FAA)