



NTSB ERA22LA183

Experimental Amateur Built A600 Helicopter, N272AM


Investigative Photographs



Photo 1: Overview of the helicopter as observed during the recovery (Photo Courtesy of FAA)



Photos 2, 3: Overview of the helicopter as observed during the recovery (Photo Courtesy of FAA)



Photos 4, 5: Turbo air intake hose clamp and the turbocharger missing its clamp (Photo Courtesy of Pilot)