



Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA186



Photo 1 – View of airplane from left wingtip (Photo courtesy of FAA)



Photo 2 – View of airplane from tail (Photo courtesy of FAA)



Photo 3 – View of left wing root and fuselage damage (Photo courtesy of FAA)



Photo 4 – View of the left wingtip where it contacted the grass (Photo courtesy of FAA)



Photo 5 – View of airplane from right rear (Photo courtesy of FAA)



Photo 6 – View of damage at the right wing root and fuselage (Photo courtesy of FAA)