

ERA23LA206

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of wrecked airplane (Courtesy of FAA)



Photograph 2 - Rear view of airplane looking forward (Courtesy of FAA)



Photograph 3 - Examination of the main fuel tank showing no fuel (Courtesy of FAA)