

ERA23LA211

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Propeller (Courtesy of FAA)



Photograph 3 - Right Side View (Courtesy of FAA)



Photograph 4 - Aft Fuselage (Courtesy of FAA)



Photograph 5 - Aft View (Courtesy of FAA)



Photograph 6 - Nose Landing Gear (Courtesy of FAA)



Photograph 7 - Nose Landing Gear Mounting Location (Courtesy of FAA)