

ERA23LA225

INVESTIGATION PHOTOGRAPHS



Figure 1: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Figure 2: Overview of the airplane at the accident site and initial impact area (Photo Courtesy of FAA)



Figure 3: View of the propeller after the airplane had been moved to the ramp at the accident airport (Photo Courtesy FAA)



Figure 4: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Figure 5: View of the airplane recovered to the ramp at the accident airport (Photo Courtesy of FAA)