



Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA232



Photo 1 – View of airplane from right wing (photo courtesy of FAA)



Photo 2 – View of airplane from front (photo courtesy of pilot)



Photo 3 – View of airplane from rear with dried fuel on left wing flap (photo courtesy of pilot)



Photo 4 – View of left wing fuel drain sump in up and locked “OPEN” position