



Photo 1 – Helicopter at Accident Site (FAA)



Photo 2 – Helicopter at Accident Site (FAA)




Photo 3 – Fractured Control Linkage at Main Rotor Hub (Cyclic) (FAA)



Photo 4 – Tail Rotor Control Linkage (FAA)



Photo 5 - Tail Rotor Control Linkage (FAA)