

ERA23LA240

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Main Wreckage (Courtesy of FAA)



Photograph 2 - Aft View of Main Wreckage (Courtesy of FAA)



Photograph 3 - Main Wreckage Recovered



Photograph 4 - Elevator Trim Actuator Measurement



Photograph 5 - Engine And Propeller