



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA243



Photo 1 – View of Accident Airplane from Right Rear (Courtesy of Pilot)



Photo 2 – View of Airplane From Right Side – Note Engine On Left (Courtesy of Pilot)



Photo 3 – View of Airplane’s Engine and Firewall, Separated From Airplane (Courtesy of Pilot)