

ERA23LA253

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Blue and white accident airplane showing fuselage damage
(Courtesy of FAA)**



**Photograph 2 - Left side of blue and white accident airplane showing left wing damage
(Courtesy of FAA)**



**Photograph 3 - View of the bridle cable block against F.S. 179
(Courtesy of NTSB)**