

NTSB ERA23LA282

N734YD, Cessna 172N

Photo Array



Photo 1: View of the airplane at the accident site. (Photo Courtesy of FAA)



Photo 2: View of substantial damage to the right horizontal stabilizer (Photo Courtesy of FAA)



Photo 3: View of substantial damage to the right horizontal stabilizer (Photo Courtesy of FAA)