



Photo 1 – Left side View of Airplane (Clearwater Airport Personnel)



Photo 2 – Water Drained from Right Wing Fuel Tank (FAA)



Photo 3 – Right Wing Fuel Tank with Corrosion (FAA)