



Photo 1 – View Of Main Wreckage as Found (AAR)



**Photo 2 - View of Main Wreckage with Separated Tail and Tailrotor Gearbox and Tailrotor Assembly in Foreground.
(AAR)**



Photo 3 – View of Main Wreckage and Damaged Main Rotor Blades (AAR)