

ERA23LA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left profile view of damaged airplane. (Courtesy of Operator)



Photograph 2 - Left aft view of damaged airplane. (Courtesy of Operator)



Photograph 3 - Front view of damaged airplane. (Courtesy of Operator)



Photograph 4 - Ground scars leading up to main wreckage. (Courtesy of Operator)