



Photo 1 – FAA Digital Photograph. View of the Cockpit Showing the Structural Damage near the Pilot's Right Rudder Pedal