

ERA23LA301

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Hull of airplane (Courtesy of FAA)



Photograph 2 - Flap and wing buckling (Courtesy of FAA)



Photograph 3 - Bottom of airplane hull bucking (Courtesy of FAA)