



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA23LA302



Photo 1 – View of Accident Airplane On Scene (Courtesy of FAA)



Photo 2 – View of Fuselage Damage (Courtesy of Pilot)