



Photo 1 – View of Leading Edge and Wing Skin Damage (MGSU)



Photo 2 – View of Damaged Wing Ribs (MGSU)