

NTSB ERA23LA305

N271MG, Piper PA-28-181

Photo Array



Photo 1: View of the damage to the right wing. (Photo Courtesy of FAA)



Photo 2: View of the damage to the right wing. (Photo Courtesy of FAA)