

ERA23LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)




Photograph 2 - Main Wreckage (Courtesy of FAA)




Photograph 3 - Cockpit Fuel Selector (NTSB Photo)



Photograph 4 - Dual Magneto (NTSB Photo)



Photograph 5 - Fuel Manifold (NTSB Photo)



Photograph 6 - Engine-driven Fuel Pump (NTSB Photo)



Photograph 7 - Fuel Strainer (NTSB Photo)