



Photo 1 – FAA Digital Photograph. Right Side View of the Inverted Airplane at the Accident Site. Note the Extended Right Flap.



Photo 2 - FAA Digital Photograph. Left Side View of the Inverted Airplane at the Accident Site.



Photo 3 – FAA Digital Photograph. Front View of the Inverted Airplane at the Accident Site.



Photo 4 - FAA Digital Photograph. Right Side View of the Inverted Airplane at the Accident Site. Note the Nearly Separated Aft Empennage.



Photo 5 - FAA Digital Photograph. View Taken Near Main Wreckage Looking Towards Departure End of Runway 13.



Photo 6 - FAA Digital Photograph. View Showing Fractured Tree Limbs.