


ERA23LA326

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Structure (Courtesy of FAA)



Photograph 2 - Main Wreckage (Courtesy of FAA)



Photograph 3 - Structure Arm (Courtesy of FAA)



Photograph 4 - Structure Arm Close-up (Courtesy of FAA)